

Easy

Assistant Engineer (Electrical), Class 2025

Building Department

_____ finds the deterioration or failure due to internal discharges caused in the insulation of bushing.

A

Power-factor voltage test

B

Internal or partial discharge test

Correct

C

Visible discharge test

D

Momentary withstand test

Correct Answer: B

Full Detailed Explanation

Open the live question URL below to read the full explanation, related links and practice flow.

Open live question on website:

<https://sarkariresultout.com/pyq/hi/question/gpsc-ae-electrical-q232-partial-discharge-in-bushings/>