

Medium

Deputy Executive Engineer (Electric)

2026

ports Authority of Gujarat / Assistant Engineer (El

Consider the following statements regarding Transfer Function: 1. Transfer function is defined as ratio of Laplace transform of output to input under zero initial

A

1, 2 and 3 only

B

1 and 3 only

C

2 and 3 only

D

1, 3 and 4 only

Correct

Correct Answer: D

Full Detailed Explanation

Open the live question URL below to read the full explanation, related links and practice flow.

Open live question on website:

<https://sarkariresultout.com/pyq/hi/question/poles-zeros-and-zero-initial-conditions/>